




PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022




Facility Name & Address: LCN Industries , Chittoor	Audited On: 09-09-2025
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. Chanukya Naidu	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 9440274003	PC Experts Contact Person No: 8248672110




FACILITY SURROUNDING




Facility Surrounding thick vegetation observed.





External Premises			REVIEW DATE	COMPLETION DATE
	Location	Factory backside gate		
	Cleaning / sanitation & Housekeeping Issues	Nil		
	Structural Issue (Pest harbourages)	Gate bottom and gate sides gaps observed		
	Access Issues	Nil		
	Description of Pest Infestation	It is Serious Threat for Ants, Rodents, lizards, snakes and other crawling insects		
	Any other observations	Nil		
	Preventive Action suggested to customer	Gap should be closed with metal sheets or mesh or rubber beading.		
	Curative action from	We are instructed to Technician for Regular Monitoring.		




1		Location	Backside gate near (left side slab bottom Gap area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Slab bottom Gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, Rodents, lizards, snakes flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
2		Location	Main building all hygiene and materials receiving area.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	All entry points PVC strips and Aircutains not fixed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, cockroaches, Rodents, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	All entry points should be placed PVC strips and Aircutains without any gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Main building cable trench area (Salt and sugar).		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall to Cable trench surroundings Gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

4		Location	Main building outer area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall to wall metal sheets between gaps noticed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards, flying insects and other crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement or form sealent.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
5		Location	Main building outer area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall to wall metal sheets between gaps noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, lizards, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement or form sealent without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
6		Location	Main building backside area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gap noticed between the wall to wall brick		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

7		Location	Main building outer AHU line area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	AHU surroundings to wall metal sheets gap noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards, flying insects and other crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
8		Location	Main building outer area (ss pipes line area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	SS pipe to Wall metal sheet gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles lizards flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with proper material like form sealent,		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
9		Location	Main emergency door exit area.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door frame to Wall gap noticed and door bottom Gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed rubber beading and cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

10		Location	Emergency door backside (cable switch box area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Switch box wire line pipe gaps noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Switch box should be placed with top switch box frame		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
11		Location	Main building (water outlet pipe line)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Pipe lid not placed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, mosquito, beetles lizards flying insects and other crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Mesh type lid should be placed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
12		Location	Main building outer area (vessels back side)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Hole observed on the Wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards and other crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Hole should be closed with cement		
		Curative action from	Nil		

13		Location	Main building (emergency door)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Emergency door frame to Wall gap noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants. Beetles, lizards and other		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
14		Location	Main building (outer emergency area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door top side corner Gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles. Lizard, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
15		Location	Main building backside (vessels backside area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	pipe hole not closed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flying insects, mosquito and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Hole should be closed with pipe lid		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
16		Location	Main building outer area (AHU line area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	AHU line surroundings gaps noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles,ants, lizards, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

17		Location	Main building backside area (vessels area backside)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Hole observed in Wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants., lizards, Rodents, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Hole should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
18		Location	Main building backside (FG outer area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	PVC strips and Aircutains not fixed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, lizards, ant, flying insects cockroaches and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	All entry points should be placed PVC strips and Aircutains without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
19		Location	Main building (cable trench line area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Cable trench line to wall between gaps noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, Rodents, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Hole should be closed from sealent or cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

Note: fly catcher machines 13 nos required.

For Pest Control Experts


Authorized Signature.

Name: SURESH KUMAR.V

Designation: MANAGER

Emp.Code: 002

Phone Number: 8248672110



For M/s. LCN Industries ,

Authorized Signature.

Name:

Designation:

Emp.Code:

Phone Number: