




## PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,  
NH 46 Service Road(Chennai to Bangalore Highway),  
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in  
Cell: 9087200011 ; 9087200022




Facility Name & Address: LCN INDUSTRIES , Chittoor	Audited On: 09-09-2025
Audited By: SURESH KUMAR.V	
Client Contact Person Name: mr.chanukya Naidu	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 9440274003	PC Experts Contact Person No: 8248672110




### FACILITY SURROUNDING




facility Surrounding thick vegetation observed




Internal Premises				REVIEW DATE	COMPLETION DATE
1		Location	Factory main gate		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Main bottom and surroundings gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, snakes, dogs, Rodents and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be with metal sheets or mesh or rubber beading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		




2		Location	COMPOUND WALL IN SIDE		
		Cleaning / sanitation & Housekeeping Issues	Tree branches fall down on the Wall		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, Rodents, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Tree branches should be trimmed on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Backside gate		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gate bottom and surroundings gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, Rodents, lizards, dogs, snakes		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with metal sheets or mesh or rubber beading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	Main building backside ( near backside gate)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Slap bottom gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, cockroaches, lizards, Rodents, mosquito and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

5		Location	Main building outer area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall to Wall metal sheets joint we observed the gaps.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, ants, lizards, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent or cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
6		Location	Main building outer area ( cable trench line)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Cable trench line to wall having a hole gaps		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, Rodents, snakes, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Cable Trenches hole will be Properly Closed.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
7		Location	Main building outer area ( power panel room outer)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Cable trench line to wall having gaps		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, Rodents, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent or cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

8		Location	Main building backside area ( vessels washing outer area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall hole observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Hole should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
9		Location	Main building backside area ( vessels washing backside)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Pipe was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, mosquito, ants, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Pipe line gap should be closed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
10		Location	Main building backside area.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall hole observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, Rodents, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Hole should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

11		Location	Main building backside area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall metal sheets to All SS pipe line surroundings having gaps		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, flying insects, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gaps should be closed with form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
12		Location	Main hygiene entrance		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	All entry points we observed no PVC strips and Aircutains		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards Rodents, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	All entry points should be placed PVC strips and Aircutains without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
13		Location	Main building backside door area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door bottom Gaps observed And no PVC strips and Aircutains.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, lizards flying insects and		
		Any other observations	Nil		
		Preventive Action suggested to customer	All entry points should be placed PVC strips and Aircutains		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

14		Location	Emergency door frame to Wall gap noticed		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Frame surroundings gaps observed and bottom also gap noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards, cockroaches mosquito and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement and rubber beading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
15		Location	Vessels washing backside		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Switch box opend condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants beetles, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Switch box lid should be placed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
16		Location	Emergency main exit		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door bottom and door surroundings gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, ants lizards flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with metal sheets		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

17		Location	Main building outer (AHU line)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	AHU line to Wall sheets gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants beetles, flying insects, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
18		Location	Main emergency exit area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall to wall sheet gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, ants lizards flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with metal sheets		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
19		Location	Main building backside outer area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall to wall metal sheets between gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

**Note: fly catcher machines 13 nos required.**

**For Pest Control Experts**


**Authorized Signature.**

**Name: SURESH KUMAR.V**

**Designation: MANAGER**

**Emp.Code: 002**

**Phone Number: 8248672110**



**For M/s. LCN INDUSTRIES ,**

**Authorized Signature.**

**Name:**

**Designation:**

**Emp.Code:**

**Phone Number:**