










Facility Name & Address: Sri Varsha Food park , Tirupati	Audited On: 19-09-2023
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. senthil	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 9940284651	PC Experts Contact Person No: 9087200011




## FACILITY SURROUNDING

Facility Surrounding lot of waste and thick vegetation observed.



Internal Premises				REVIEW DATE	COMPLETION DATE
1		Location	Fruit waste outlet conveyor line area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Conveyor lid not closed properly.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, cockroach, lizard, flying insects and other crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Properly closed lid without any gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
2		Location	Fruit Waste Outlet area window		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Window frame to windows gaps observed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, cockroach, lizard and flying insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber breading or pvc brush.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

3		Location	Fruit waste outlet conveyor near window		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Window frame to windows doors gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizard, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber breading or pvc brush		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	Window frame		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Window frame to Wall gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, spider and other crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	It should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
5		Location	Emergency exit door area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Doors to doors frame gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, spider, lizard and crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Doors should be closed without any gaps		
		Curative action from	W		
6		Location	All Exhaust fan area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Exhaust fan in side gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, flying insects, lizards and other crawling insects		
		Any other observations	Exhaust fan frame also hole observed		
		Preventive Action suggested to customer	It should be closed with mesh		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

7		Location	Dispatch area shutter		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Dispatch area shutter gap observed between the shutter to wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizard, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber breading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
8		Location	Fruit Washing area door bottom		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Fruit Washing area door bottom gaps observed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizard and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber breading or pvc brush		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
External Premises				REVIEW DATE	COMPLETION DATE
1		Location	Main building back side area		
		Cleaning / sanitation & Housekeeping Issues	Lot of used materials kept at main building Wall side.		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for snakes, rodent, lizards, Ants and crawling insects it will be hide in this place.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't allow the materials at main building surrounding.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

2		Location	Compound wall		
		Cleaning / sanitation & Housekeeping Issues	We observed lot of thick vegetation.		
		Structural Issue (Pest harbourages)	Compound wall construction work going on.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for snake, rodent, forest animals, lizard and other crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Compound wall should be required		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Chemical Room Out side area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	We observed the gaps between the wall to sheet		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards flying insects, beetles and other crawling insects will be hide in this place.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	Ammonia plant office out side.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	AC pipe hole not closed properly		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards flying insects and crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Ac pipe hole should be closed with cement.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
5		Location	Power panel shutter area.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps Observed between shutter and floor		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, rodent, snake flying insects and other crawling insects		
		Any other observations	Shutter centre also Holes observed		
		Preventive Action suggested to customer	Bottom of shutter should be placed rubber beading and shutter holes should be closed with mesh or SS metal sheet		
		Curative action from	We are instructed to Technician for Regular Monitoring.		



6		Location	Ammonia plant shutter area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Ammonia plant shutter was opened.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, flying insects, lizards, snake, rodent and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	It should be closed always.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
7		Location	Fruit feeding conveyor line area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Fruit feeding conveyor belt under We observed gaps.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, flying insects and other crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement or metal sheet		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

**Note: compound wall required**

For Pest Control Experts


Authorized Signature.

Name: SURESH KUMAR.V

Designation: MANAGER

Emp.Code: 002

Phone Number: 9087200011



For M/s. Sri Varsha Food park ,

Authorized Signature.

Name:

Designation:

Emp.Code:

Phone Number: