

PEST CONTROL EXPERTS

No.6, 1st Floor, Balaji Lodge Complex, NH 46 Service Road(Chennai to Bangalore Highway), Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in Cell: 9087200011; 90872000022

Facility Name & Address: CG Foods India Pvt Ltd , Chittoor	Audited On: 28-09-2023
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr.Nirjan	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 9502481441	PC Experts Contact Person No: 9087200011

FACILITY SURROUNDING

facility Surrounding lot of thick vegetation observed.

	External Premises		REVIEW DATE	COMPLETION DATE
	Location	Fencing area		
	Cleaning / sanitation & Housekeeping Issues	Lot of thick vegetation observed.		
	Structural Issue (Pest harbourages)	No compound wall		
	Access Issues	Nil		
		It is Serious Threat for snakes, Rodents, lizards,		
1	Description of Pest Infestation	monkeys, spiders, Ants flying insects and other		
A STATE OF THE STA		crawling insects.		
	Any other observations	Nil		
	Preventive Action suggested to customer	Facility Surrounding compound wall required. Thick		
THE PROPERTY OF THE PARTY OF TH	Preventive Action suggested to customer	vegetation should be clean on regular basis.	ılar basis.	
And the second of the second o	Curative action from	We are instructed to Technician for Regular Monitoring.		
	Location	Fencing area		
A STATE OF THE STA	Cleaning / sanitation & Housekeeping Issues	Lot of water stagnated		
	Structural Issue (Pest harbourages)	Nil		
	Access Issues	Nil		
2	Description of Pest Infestation	It is Serious Threat for mosquitoes, beetles, Ants, flying		
	Description of Fest Intestation	insects and other crawling insects.		
	Any other observations	Nil		
	Preventive Action suggested to customer	Don't allow the water stagnated facility Surrounding.		
	Curative action from	We are instructed to Technician for Regular Monitoring.		

		Location	Main building back side	
		Cleaning / sanitation & Housekeeping Issues	Water stagnated	
		Structural Issue (Pest harbourages)	Nil	
		Access Issues	Nil	
_	The second secon		It is Serious Threat for Beetles, mosquitoes, flying	
3		Description of Pest Infestation	insects and other crawling insects.	
		Any other observations	Nil	
		·	Don't allow the water stagnated inside the facility	
		Preventive Action suggested to customer	Surrounding.	
		Curative action from	We are instructed to Technician for Regular Monitoring.	
	MANAGEMENT OF THE PARTY OF THE	Location	Main building back side.	
		Cleaning / sanitation & Housekeeping Issues	Lot water stagnated	
		Structural Issue (Pest harbourages)	Nil	
		Access Issues	Nil	
		Description of Boot Infortation	It is Serious Threat for Beetles, flying insects,	
4		Description of Pest Infestation	mosquitoes and other crawling insects.	
		Any other observations	Nil	
			Don't allow the water stagnated inside of facility	
		Preventive Action suggested to customer	Surrounding.	
		Curative action from	We are instructed to Technician for Regular Monitoring.	
		Location	Main building back side	
	The state of the s	Cleaning / sanitation & Housekeeping Issues	Waste oil spillage observed and not cleaned properly.	
		Structural Issue (Pest harbourages)	Nil	
	Control of the second	Access Issues	Nil	
5	A THE RESERVE OF THE PARTY OF T	Description of Pest Infestation	It is Serious Threat for Beetles.	
		Any other observations	Employee May be fall down	
		Proventive Action suggested to sustamer	Don't allow oil spillage and always keep dry conditions.	
		Preventive Action suggested to customer	Make a danger barricades	
		Curative action from	We are instructed to Technician for Regular Monitoring.	
		Location	Main building back side area	
	Marilla Comment	Cleaning / sanitation & Housekeeping Issues	Waste Dumped near by facility Surrounding	
	HA	Structural Issue (Pest harbourages)	Nil	
		Access Issues	Nil	
6		Description of Pest Infestation	It is Serious Threat for Ants, cockroach, rodent, lizard,	
		Description of Fest Intestation	monkeys, flying insects and other crawling insects.	
		Any other observations	Nil	
			Don't allow the waste materials near by facility	
		Preventive Action suggested to customer	Surrounding. Waste material dumping purpose Separate	
	罗普·勒		area to be allotted.	
		Curative action from	We are instructed to Technician for Regular Monitoring.	

		Location	Main building back side.	
		Cleaning / sanitation & Housekeeping Issues	Lot of hot water stagnated.	
	1		Hot water pipe line was damaged, so that hot water fall	
		Structural Issue (Pest harbourages)	down.	
		Access Issues	Nil	
7			It is Serious Threat for Beetles, flying insects and other	
	Town T	Description of Pest Infestation	crawling insects.	
		Any other observations	Nil	
			Pipe should be replaced.Pipe should be replaced. Don't	
		Preventive Action suggested to customer	allow the fall down the hot water.	
		Curative action from	We are instructed to Technician for Regular Monitoring.	
		Location	Hygiene entrance area	
		Cleaning / sanitation & Housekeeping Issues	Manhole not cleaned properly.	
		Structural Issue (Pest harbourages)	Manhole was opened condition.	
		Access Issues	Nil	
		Description of Boot Infortation	It is Serious Threat for Cockroaches, mosquitoes, flying	
8		Description of Pest Infestation	insects, Ants, and other crawling insects.	
		Any other observations	Nil	
		Preventive Action suggested to customer	Manhole should be closed with manhole lid without any	
		Preventive Action suggested to customer	gaps.	
		Curative action from	We are instructed to Technician for Regular Monitoring.	
		Location	Hygiene entrance toilet area.	
		Cleaning / sanitation & Housekeeping Issues	Not cleaned regularly. It's worst condition.	
	2 ->	Structural Issue (Pest harbourages)	Toilet exhaust gaps observed. Toilet doors not closed	
		off detail is sue (i est flat bourages)	properly and gaps observed.	
		Access Issues	Nil	
9		Description of Pest Infestation	It is Serious Threat for Cockroaches, bacteria, fungal,	
"		Description of rest intestation	lizard, flying insects and other crawling insects.	
		Any other observations	Nil	
	1 1		All toilet area must be clean on regular basis. Doors	
		Preventive Action suggested to customer	also should be closed. All gaps should be closed with	
	A STORY		rubber breading, cement and mesh.	
	14.16	Curative action from	We are instructed to Technician for Regular Monitoring.	

		Location	Main building outer surface	
		Cleaning / sanitation & Housekeeping Issues	Lot of thick vegetation observed	
		Structural Issue (Pest harbourages)	Nil	
		Access Issues	We can't able to monitoring the boxes.	
10		Description of Boot Infortation	It is Serious Threat for Beetles, snakes, rodents, lizards,	
		Description of Pest Infestation	Ants, frog and other crawling insects	
		Any other observations	Nil	
		Preventive Action suggested to customer	Thick vegetation should be clean on regular basis.	
		Curative action from	We are instructed to Technician for Regular Monitoring.	
		Location	Main building surrounding area	
		Cleaning / sanitation & Housekeeping Issues	Lot of thick vegetation observed	
		Structural Issue (Pest harbourages)	Nil	
		Access Issues	Nil	
11		Description of Pest Infestation	It is Serious Threat for Beetles, Ants, cockroach,	
		Description of Fest Intestation	snakes, rodents, lizards and other crawling insects.	
		Any other observations	Nil	
		Preventive Action suggested to customer	Thick vegetation should be clean on regular basis.	
		Curative action from	We are instructed to Technician for Regular Monitoring.	
		Location	Hygiene entrance area	
		Cleaning / sanitation & Housekeeping Issues	Floor not cleaned properly	
		Structural Issue (Pest harbourages)	Hygiene entrance doors always opend condition. Not	
		Structural issue (Fest Harbourages)	closed properly.	
		Access Issues	Nil	
		Description of Pest Infestation	It is Serious Threat for Ants, cockroach, flying insects,	
		Description of rest intestation	rodents, snakes, lizards and other crawling insects.	
12			Doors frame to doors gaps observed. Toilet exhaust fan	
		Any other observations	mesh not fixed properly.in this area gaps observed	
		Any other observations	between the wall to Wall Sheet and Wall Sheet to roof	
			sheet.	
	The Control of the Co		Floor should be clean on regular basis. All gaps should	
		Preventive Action suggested to customer	be closed with cement or rubber breading or Mesh	
			without any gaps.	
	· · · · · · · · · · · · · · · · · · ·	Curative action from	We are instructed to Technician for Regular Monitoring.	

		Location	RM area	1
			Nil	
		Cleaning / sanitation & Housekeeping Issues		
	No.	Structural Issue (Pest harbourages)	RM area shutter was damaged condition	
	A selection of the	Access Issues	Nil	
			It is Serious Threat for Beetles, lizard, spiders, rodents,	
		Description of Pest Infestation	Ants, snakes, dogs, frogg, flying insects and other	
13			crawling insects.	
		Any other observations	2nd shutter also gaps observed between the shutter to	
		7 and observations	shutter frame	
			Shutter should be placed without any gaps. Bottom of	
		Preventive Action suggested to customer	shutter should be placed rubber beading without any	
			gaps.	
		Curative action from	We are instructed to Technician for Regular Monitoring.	
		Location	FG area	
	\$ 1 m	Cleaning / sanitation & Housekeeping Issues	Nil	
		S	FG area shutter was damaged condition, lot of gaps	
		Structural Issue (Pest harbourages)	observed and shutter was opened condition.	
			In FG area all FG material kept at wall side without any	
		Access Issues	gaps.	
14			It is Serious Threat for Ants, cockroach, lizard, rodent,	
		Description of Pest Infestation	snake, flying insects and other crawling insects.	
			In side of FG area all materials kept at wall side without	
		Any other observations	gaps.	
	Track Control of the Control		Shutter should be replaced. Shutter gaps closed with	
		Preventive Action suggested to customer	rubber breading or mesh or cement without any gaps.	
		Curative action from	We are instructed to Technician for Regular Monitoring.	
		Location	Hygiene entrance toilet area.	
		Cleaning / sanitation & Housekeeping Issues	Toilets not cleaned properly	
		Structural Issue (Pest harbourages)	Mesh not fixed on Exhaust fan.	
		Access Issues	Nil	
15		Access issues	It is Serious Threat for Cockroaches, Ants, beetles,	
15		Description of Pest Infestation		
		Association of considerations	lizard, flying insects and other crawling insects.	
		Any other observations	Nil	
		Preventive Action suggested to customer	Mesh to be placed without any gaps.	
	: 1	Curative action from	We are instructed to Technician for Regular Monitoring.	

	Location	RM shutter area	
	Cleaning / sanitation & Housekeeping Issues	Nil	
	Structural Issue (Pest harbourages)	Gaps observed between the Shutter frame to Wall	
ALC:	Access Issues	Nil	
16		It is Serious Threat for Beetles, Ants, cockroach, lizard,	
	Description of Pest Infestation	flying insects and other crawling insects.	
	Any other observations	Nil	
	Preventive Action suggested to customer	Gap should be closed with cement concrete	
	Curative action from	We are instructed to Technician for Regular Monitoring.	
	Location	Hygiene entrance area	
	Cleaning / sanitation & Housekeeping Issues	Nil	
	Structural Issue (Pest harbourages)	Wall sheet opened condition	
17	Access Issues	Nil	
	Description of Pest Infestation	It is Serious Threat for Ants, beetles, flying insects,	
	Description of Fest Intestation	lizards and other crawling insects.	
	Any other observations	Nil	
	Preventive Action suggested to customer	Sheet to be placed without any gaps	
	Curative action from	We are instructed to Technician for Regular Monitoring.	

Note: surrounding compound wall required.

For Pest Control Experts

Authorized Signature.

Name: SURESH KUMAR.V

Designation: MANAGER

Emp.Code: 002

Phone Number: 9087200011

For M/s. CG Foods India Pvt Ltd,

Authorized Signature.

Name:

Designation:

Emp.Code:

Phone Number: