

PEST CONTROL EXPERTS

No.6, 1st Floor, Balaji Lodge Complex, NH 46 Service Road(Chennai to Bangalore Highway), Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in Cell: 9087200011; 90872000022

Facility Name & Address: IFF , Sricity	Audited On: 21-11-2023	
Audited By: SURESH KUMAR.V		
Client Contact Person Name: Mr. Bhanu	PC Experts Contact Person Name: SURESH KUMAR.V	
Client Contact Person No: 8433294204	PC Experts Contact Person No: 9087200011	

FACILITY SURROUNDING

nil

Internal Premises			REVIEW DATE	COMPLETION DATE	
GX3R+J4, 3ri City, Let 13.506142*		Location	RM Emergency exit door		
		Cleaning / sanitation & Housekeeping Issues	Nil		
	English Andrea Frederick F	Structural Issue (Pest harbourages)	Gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, millipede,		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber breading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
External Premises			REVIEW DATE	COMPLETION DATE	

Location	RM Emergency Exit Area		
Cleaning / sanitation & Housekeeping Issues	Nil		
Structural locus (Boot horbourges)	Door frame to floor and door frame to doors gaps		
Structural Issue (Pest harbourages)	observed.		
Access Issues	RM Emergency doors regularly using man movement,		
Access issues	so it was not closed properly.		
Description of Pest Infestation	It is Serious Threat for Ants, millipede and other crawling		
Description of Fest infestation	insects.		
Any other observations	Nil		
Proventive Action averaged to evetemen	Gap should be closed with rubber breading or silicone		
Preventive Action suggested to customer	sealant.		

		We are instructed to Technician for Regular Monitoring.		
	Location	RM Emergency exit door.	1	
	Cleaning / sanitation & Housekeeping Issues	Nil	1	
	Structural Issue (Pest harbourages)	Gap observed between the doors to doors frame.	1	
	Access Issues	Nil	1	
2	Description of Pest Infestation	We observed live millipede out side of the building.	!	
□ GPS Map Camera	Any other observations	Due to rain all crawling insects come and hide some places like cracks and gaps area.	!	
Sri City, Andhra Pradesh, India OX3R-44, 5n City, Andhra Pradesh 517646, India Lat 13,000112* Long 79,0893995* Google 21(1)(23,123) PM GMT 105:30	Preventive Action suggested to customer	In this area where ever cracks and gaps identified that area should be closed with cement concrete.	<u> </u>	
	Curative action from	We are instructed to Technician for Regular Monitoring.		
	Note	nil	!	
For Pest Control Experts		For M/s. IFF ,		
Authorized Signature.		Authorized Signature.	!	
		_	!	
Name: SURESH KUMAR.V	111	Name:	!	
Designation: MANAGER	1. Juna Dans	Designation:	!	
Emp.Code: 002		Emp.Code:	!	
•	Curative action from		!	
Phone Number: 9087200011		Phone Number:		

GPS Map Camera

Sri City, Andhra Pradesh, India GX3R+J4, 5ri City, Andhra Pradesh 517646, India Lat 13.506032°

Long 79.989402" 21/11/23 12:40 PM GMT + 05:30