




PEST CONTROL EXPERTS





No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022




Facility Name & Address: Sri Varsha Integrated Food Park Pvt Ltd , Kodur, Kadapa Dist,	Audited On: 22-01-2024
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. Sendhil QC	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 9940284651	PC Experts Contact Person No: 8248672110




FACILITY SURROUNDING




Forest Area. we observed lot of thick vegetation

Internal Premises				REVIEW DATE	COMPLETION DATE
1		Location	Fruit Washing area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	At the time of inspection Doors was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flies, other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Doors should be closed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

2		Location	Fruit waste conveyor line		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Fruit waste conveyor line lid to lid gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, flies and lizard		
		Any other observations	Nil		
		Preventive Action suggested to customer	Lid should be closed without any gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Main building Exhaust fans		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	In Exhaust fan observed gaps		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, flies and lizard		
		Any other observations	Nil		
		Preventive Action suggested to customer	Exhaust fan gaps should be closed.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	Main building (Fruit waste conveyor line near window)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Fruit waste conveyor line near window frame gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, flies and lizards		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber breading or out side should be placed mesh		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
5		Location	Main building (window frame)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Cutting conveyor line near Window frame to Wall gap observed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, flies		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap will be closed with cement mortar or Foam Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

6		Location	Dispatch area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Shutter frame to Wall gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizard		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap will be closed with Foam Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
7		Location	Dispatch area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Lifting area we observed gap		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizard, other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber breadding		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
8		Location	Dispatch area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	shutter top side gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizard and flying insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber breadding		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
External Premises				REVIEW DATE	COMPLETION DATE

9		Location	COMPOUND WALL IN SIDE		
		Cleaning / sanitation & Housekeeping Issues	Thick vegetation observed		
		Structural Issue (Pest harbourages)	Gap observed between the compound wall to wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Snakes, Rodent, lizards, Ants and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Thick vegetation should be clean on regular basis. Gap should be closed with cement concrete or rubber breading between the wall gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
10		Location	Fruit waste receiving area		
		Cleaning / sanitation & Housekeeping Issues	Waste water stagnated the near building		
		Structural Issue (Pest harbourages)	Manhole lid was damaged and not closed properly		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, flies, rodent, cockroach, mosquitoes lizard, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Manhole lid should be changed and closed properly without any gaps. Don't allow the waste water stagnated around the building surrounding		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
11		Location	Fruit waste receiving area near		
		Cleaning / sanitation & Housekeeping Issues	Waste water stagnated and don't allow the materials near by building.		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flies, cockroach, lizard, rodent, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't allow the waste water near by building. Don't keep the materials near by building surrounding		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

12		Location	Main building back side		
		Cleaning / sanitation & Housekeeping Issues	Thick vegetation observed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for snakes, rodent, beetles, lizard and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Thick vegetation should be clean on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
13		Location	Main building back side		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Unused materials stored		
		Description of Pest Infestation	It is Serious Threat for snakes, Rodent and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't Store the materials near by building surrounding		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
14		Location	Conference Hall outer		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Pipe was damaged condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Cockroaches, Ants, Rodent, other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Pipe should be replaced		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

Note:

For Pest Control Experts


Authorized Signature.

Name: SURESH KUMAR.V

Designation: MANAGER

Emp.Code: 002

Phone Number: 8248672110



For M/s. Sri Varsha Integrated Food Park Pvt Ltd ,

Authorized Signature.

Name:

Designation:

Emp.Code:

Phone Number: