




PEST CONTROL EXPERTS





No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022





Facility Name & Address: RMM FOOD PRODUCTS PRIVATE LIMITED , Chittoor	Audited On: 13-05-2024
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. Chengal Reddy	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 9441911123	PC Experts Contact Person No: 8248672110

FACILITY SURROUNDING

lot of Thick vegetation and Hill area

Internal Premises			REVIEW DATE	COMPLETION DATE	
1		Location	Main process hall		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Mesh was Damaged Condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, Lizard, cockroach and Rodent		
		Any other observations	Nil		
		Preventive Action suggested to customer	Mesh to be replaced without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

2		Location	Hygienic Entrance area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps Observed between bottom of the Door and Floor		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, flies, Lizard, cockroach		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber beading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Processing Hall		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Roof sheet to Wall gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, lizard, flies		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with silicon sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	Frozen area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Fly catcher machine not worked		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, lizard flies		
		Any other observations	Nil		
		Preventive Action suggested to customer	Fly Catcher machine should be working condition		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
5		Location	FG area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Root sheet was damaged condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizard		
		Any other observations	Nil		
		Preventive Action suggested to customer	Sheet should be replaced		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

6		Location	Processing Hall					
		Cleaning / sanitation & Housekeeping Issues	Nil					
		Structural Issue (Pest harbourages)	Roof sheet damaged					
		Access Issues	Nil					
		Description of Pest Infestation	It is Serious Threat for Ants, lizard					
		Any other observations	Nil					
		Preventive Action suggested to customer	Roof sheet should be replaced					
		Curative action from	We are instructed to Technician for Regular Monitoring.					
7		Location	Processing Hall					
		Cleaning / sanitation & Housekeeping Issues	Nil					
		Structural Issue (Pest harbourages)	Roof exhaust fan not available					
		Access Issues	Nil					
		Description of Pest Infestation	It is Serious Threat for Beetles, lizard					
		Any other observations	Nil					
		Preventive Action suggested to customer	Exhaust fan should be placed					
		Curative action from	We are instructed to Technician for Regular Monitoring.					
External Premises				REVIEW DATE	COMPLETION DATE			
8		Location	Main Gate					
		Cleaning / sanitation & Housekeeping Issues	Nil					
		Structural Issue (Pest harbourages)	Main and back side gate bottom gaps observed					
		Access Issues	Nil					
		Description of Pest Infestation	It is Serious Threat for Ants, Snakes, Rodent					
		Any other observations	Nil					
		Preventive Action suggested to customer	Bottom of the gate should be closed with rubber beading					
		Curative action from	We are instructed to Technician for Regular Monitoring.					
Note:								
For Pest Control Experts Authorized Signature. Name: SURESH KUMAR.V Designation: MANAGER Emp.Code: 002 Phone Number: 8248672110						For M/s. RMM FOOD PRODUCTS PRIVATE LIMITED , Authorized Signature. Name: Designation: Emp.Code: Phone Number:		