








Facility Name & Address: LCN INDUSTRIES , Chittoor	Audited On: 09-09-2025
Audited By: SURESH KUMAR.V	
Client Contact Person Name: mr.chanukya Naidu	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 9440274003	PC Experts Contact Person No: 8248672110




FACILITY SURROUNDING




facility Surrounding thick vegetation observed




Internal Premises				REVIEW DATE	COMPLETION DATE
1		Location	Allergens packing material store 1st floor		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall to wall metal sheet gap observed & cooling sheets was damaged condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, spider, lizards flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent and replace the cooling sheets or sealed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

2		Location	FG store area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Bottom of the gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber beading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Packing material store 1st floor		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Roof sheet joint corner we observed the gaps (both sides).		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, spiders, beetles, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gaps should be closed with form sealent.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	FG and allergens store		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	FG and allergens store between window frame near wall was damaged condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, cockroaches		
		Any other observations	Nil		
		Preventive Action suggested to customer	Damaged area will be plastered.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

5		Location	Allergens area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Holes was observed on wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, beetles and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Holes should be closed with white cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
6		Location	Middle wall of the window from allergen to salt and sugar area.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Opened condition (mesh not fixed).		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Mesh window should be placed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
7		Location	Packing material store (1st floor)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall sheet to wall between gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, flying insects, beetles and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent or cement without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

8		Location	Blender to 2nd packing are (steps area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall to from sheet between gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards, and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
9		Location	Blender area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Cable trench to wall between gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, Rodents, lizards, other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent or cement without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
10		Location	Sugar grinding area		
		Cleaning / sanitation & Housekeeping Issues	Cobweb observed between the machine to 1st slap		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, spider		
		Any other observations	Nil		
		Preventive Action suggested to customer	Web should be clean on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

11		Location	Blender area (AHU line)		
		Cleaning / sanitation & Housekeeping Issues	Dust accumulated		
		Structural Issue (Pest harbourages)	AHU line to wall sheet between gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, flying insects, lizards and spider		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
12		Location	Vessels washing area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Window frame to wall between gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, flying insects, lizards, ants and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
13		Location	Salt and sugar receiving area (shutter bottom)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Shutter bottom gap noticed		
		Access Issues	NIL		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Shutter bottom rubber beading should be placed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

14		Location	Salt and sugar unloading area		
		Cleaning / sanitation & Housekeeping Issues	Spider Web observed		
		Structural Issue (Pest harbourages)	Roof corner we observed the gaps		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, spider, lizards flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Spider Web should be clean on regular basis. Gap should be closed with form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
15		Location	Vessels washing area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Roof top gap noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flying insects lizards, spider beetles and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
16		Location	Blender packing material store area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Cooling sheets damaged and cooling sheets not sealed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, spider, lizards, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Cooling sheets should be seal it, damaged palced should be paste it.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
Note: fly catcher machines 13 nos required.					

For Pest Control Experts


Authorized Signature.

Name: SURESH KUMAR.V

Designation: MANAGER

Emp.Code: 002

Phone Number: 8248672110

A handwritten signature in blue ink, appearing to read 'Suresh Kumar.V', is written over a light gray rectangular background.

For M/s. LCN INDUSTRIES ,

Authorized Signature.

Name:

Designation:

Emp.Code:

Phone Number: