




PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022




Facility Name & Address: Navya Foods Pvt Ltd , Chittoor	Audited On: 27-05-2024
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. Raghavendra (QH)	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 9441588044	PC Experts Contact Person No: 8248672110




FACILITY SURROUNDING




lot of Thick vegetation and Hill area




Internal Premises				REVIEW DATE	COMPLETION DATE
1		Location	Fruit Washing area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Conveyor line to wall gaps noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, snakes, rodent, lizard and flies		
		Any other observations	Nil		
		Preventive Action suggested to customer	Wall to conveyor line gaps should be closed permanently without any gaps (cement wall or sheet).		
		Curative action from	We are instructed to Technician for Regular Monitoring.		




2		Location	Fruit Washing area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Fruit conveyor line to wall gap noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flies, lizard and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with sheet without any gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	FG area inside		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Drums are kept wall side without any gaps		
		Description of Pest Infestation	It is Serious Threat for Ants, rodent, lizard and snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be required from wall to material atleast 2 feet from wall to material.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	Processing Hall		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Doors was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flies,. lizard and Rodent		
		Any other observations	Nil		
		Preventive Action suggested to customer	Processing Hall all window and doors should be closed without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		



5		Location	Processing Hall		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Window mesh was damaged		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, flies, lizard and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Window mesh should be replaced		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
6		Location	Processing Hall		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Window was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, flies, lizard and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Window always closed without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
External Premises				REVIEW DATE	COMPLETION DATE
7		Location	Fruit Washing area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Fruit Washing big door was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flies, rodent, lizard and snakes		
		Any other observations	Nil		
		Preventive Action suggested to customer	Door should be closed permanently without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

8		Location	Fruit Washing area out side		
		Cleaning / sanitation & Housekeeping Issues	Lot of waste stagnated the water running line		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for bettle, Flies and Ants cockroach other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Waste should be clean on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
9		Location	Power plant area out side		
		Cleaning / sanitation & Housekeeping Issues	Waste water stagnated in the manhole		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flies,. cockroach and other crawling insects		
		Any other observations	Nil		
10		Preventive Action suggested to customer	Waste water don't allow to stagnate surrounding facility, that should be clean on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
		Location	Power plant area out side		
		Cleaning / sanitation & Housekeeping Issues	Fruits pillages observed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flies		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't allow the pillages of fruit in facility area		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

11		Location	Facility in side area		
		Cleaning / sanitation & Housekeeping Issues	Lot of Thick vegetation observed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, snakes, rodent, cockroach, flies and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Thick vegetation should be trim on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
12		Location	Waste water running line area		
		Cleaning / sanitation & Housekeeping Issues	Lot of waste water stagnated in the water running line area		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flies cockroach, and other flying and crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't allow the waste water stagnate surrounding and running line area		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
13		Location	FG area		
		Cleaning / sanitation & Housekeeping Issues	Lot of drums material dumped the building wall side		
		Structural Issue (Pest harbourages)	Shutter also not closed properly		
		Access Issues	Rodent Box also completely closed with cement		
		Description of Pest Infestation	It is Serious Threat for Ants, snakes, lizard, Rodent and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Shutter should be closed godown not used time, don't allow the dumping of the material on wall side. Gap should be required from wall to material atleast 2 feet.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

14		Location	FG area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Box was closed with concrete		
		Access Issues	Rodent Box we can't able to access		
		Description of Pest Infestation	It is Serious Threat for Ants, Rodent, snakes, lizard and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Boxes always should be access any time		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
15		Location	Boiler area		
		Cleaning / sanitation & Housekeeping Issues	Lot of Thick vegetation observed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, snakes, rodent,. crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Tree branches and vegetation should be trim on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
16		Location	Drums receiving area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle Rodent, Snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Doors should be closed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

17		Location	Store area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	When we observed lot of Rodent boxes missing from the places		
		Description of Pest Infestation	It is Serious Threat for Ants,. lizard, rodent, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Rodent Boxes should purchase and place it as per diagram		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
18		Location	Drums receiving area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Pvc strip not available in this area.and when we observed Air curtain noot running.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flies Rodent and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	PVC strip should be place without any gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
19		Location	FG area		
		Cleaning / sanitation & Housekeeping Issues	Lot of waste water stagnated		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, flies, cockroach Rodent, mosquito, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't allow the waste water stagnated		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

20		Location	FG area					
		Cleaning / sanitation & Housekeeping Issues	Nil					
		Structural Issue (Pest harbourages)	Ni					
		Access Issues	Rodent Boxes was missing from the places					
		Description of Pest Infestation	It is Serious Threat for Ants, Rodent,lizard, Birds snakes and other crawling insects					
		Any other observations	Nil					
		Preventive Action suggested to customer	Boxes should be placed, shutter should be closed when man non working time					
		Curative action from	We are instructed to Technician for Regular Monitoring.					
Note:								
For Pest Control Experts Authorized Signature. Name: SURESH KUMAR.V Designation: MANAGER Emp.Code: 002 Phone Number: 8248672110						For M/s. Navya Foods Pvt Ltd , Authorized Signature. Name: Designation: Emp.Code: Phone Number:		