




## PEST CONTROL EXPERTS


No.6, 1st Floor, Balaji Lodge Complex,  
NH 46 Service Road(Chennai to Bangalore Highway),  
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in  
Cell: 9087200011 ; 9087200022

|  |  |
|--|--|
| Facility Name & Address: hostel , trichy | Audited On: 30-01-2024                         |
| Audited By: SURESH KUMAR.V               |  |
| Client Contact Person Name: sakthi       | PC Experts Contact Person Name: SURESH KUMAR.V |
| Client Contact Person No: 9632545258     | PC Experts Contact Person No: 9087200011       |

### FACILITY SURROUNDING

surrounding

| Internal Premises |  |   |  | REVIEW DATE | COMPLETION DATE |
|-------------------|--|---|--|-------------|-----------------|
| 1                 |  | Location                                    | AMMONIA ROOM AREA  | 30-01-2024  | 30-01-2024      |
|                   |  | Cleaning / sanitation & Housekeeping Issues | Product Spillages Noticed.   |             |                 |
|                   |  | Structural Issue (Pest harbourages)         | Crack was Observed in Floor.   |             |                 |
|                   |  | Access Issues                               | Drumps Dumped. We are not able to access.                                  |             |                 |
|                   |  | Description of Pest Infestation             | It is Serious Threat for Ants.   |             |                 |
|                   |  | Any other observations                      | Nil  |             |                 |
|                   |  | Preventive Action suggested to customer     | Around the Pipeline Gap will be closed with cement mortar or Foam Sealant. |             |                 |
|                   |  | Curative action from                        | We are instructed to Technician for Regular Monitoring.                    |             |                 |

| External Premises   |   |   |  | REVIEW DATE | COMPLETION DATE |
|---|---|---|--|-------------|-----------------|
| 1   |  | Location                                    | CHAMBERS AREA  |             |                 |
|   |   | Cleaning / sanitation & Housekeeping Issues | J  |             |                 |
|   |   | Structural Issue (Pest harbourages)         | Air Curtain not Working.   |             |                 |
|   |   | Access Issues                               | Drumps Dumped. We are not able to access.  |             |                 |
|   |   | Description of Pest Infestation             | It is Serious Threats for Flies, Lizards & Cockroaches.  |             |                 |
|   |   | Any other observations                      | Nil  |             |                 |
|   |   | Preventive Action suggested to customer     | Around the Pipeline Gap will be closed with cement mortar or Foam Sealant.                               |             |                 |
|   |   | Curative action from                        | We are instructed to Technician for Regular Monitoring.  |             |                 |
| <b>Note: important</b>  |   |   |  |             |                 |
| <b>For Pest Control Experts</b><br>Authorized Signature.<br>Name: SURESH KUMAR.V<br>Designation: MANAGER<br>Emp.Code: 002<br>Phone Number: 9087200011 |   |   | <b>For M/s. hostel ,</b><br>Authorized Signature.<br>Name:<br>Designation:<br>Emp.Code:<br>Phone Number: |             |                 |

