




PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022



Facility Name & Address: cv, gg	Audited On: 30-01-2024
Audited By: MOHAMMED YOUNUS.A	
Client Contact Person Name: gg	PC Experts Contact Person Name: MOHAMMED YOUNUS.A
Client Contact Person No: 888999 888	PC Experts Contact Person No: 9087200011

FACILITY SURROUNDING

vv

Internal Premises				REVIEW DATE	COMPLETION DATE
1		Location	FENCING AREA	30-01-2024	30-01-2024
		Cleaning / sanitation & Housekeeping Issues	Product Spillages Noticed.		
		Structural Issue (Pest harbourages)	Air Curtain not Working.		
		Access Issues	Granite Materials Dumped. We are not able to access.		
		Description of Pest Infestation	It is Serious Threats for Flies, Lizards, Spiders, & Crawling Insects.		
		Any other observations	Gv		
		Preventive Action suggested to customer	Around the Pipeline Gap will be closed with cement mortar or Foam Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

2		Location	BLENDER AREA		
		Cleaning / sanitation & Housekeeping Issues	Regular Housekeeping Team Monitor Required.		
		Structural Issue (Pest harbourages)	AC pipe hole not closed properly		
		Access Issues	Drumps Dumped. We are not able to access.		
		Description of Pest Infestation	It is Serious Threat for Ants.		
		Any other observations	H		
		Preventive Action suggested to customer	Aircurtain Air Will be Checked.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	CHAMBERS AREA		
		Cleaning / sanitation & Housekeeping Issues	Regular Housekeeping Team Monitor Required.		
		Structural Issue (Pest harbourages)	Air Curtain not Working.		
		Access Issues	Drumps Dumped. We are not able to access.		
		Description of Pest Infestation	It is Serious Threats for Flies, Lizards, Spiders, & Crawling Insects.		
		Any other observations	GGAround the Pipeline Gap will be closed with cement mortar or Foam Sealant.		
		Preventive Action suggested to customer	J		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	CANTEEN AREA	31-01-2024	30-01-2024
		Cleaning / sanitation & Housekeeping Issues	C		
		Structural Issue (Pest harbourages)	Fall Ceiling was Damaged Condition		
		Access Issues	F		
		Description of Pest Infestation	GAround the Pipeline Gap will be closed with cement mortar or Foam Sealant.		
		Any other observations	GGAround the Pipeline Gap will be closed with cement mortar or Foam Sealant.		
		Preventive Action suggested to customer	Aircurtain Air Will be Checked.		
		Curative action from	GAround the Pipeline Gap will be closed with cement mortar or Foam Sealant.		

External Premises				REVIEW DATE	COMPLETION DATE
1		Location	Bb	30-01-2024	30-01-2024
		Cleaning / sanitation & Housekeeping Issues	Bb		
		Structural Issue (Pest harbourages)	Cable trench was Opened Condition		
		Access Issues	Granite Materials Dumped. We are not able to access.		
		Description of Pest Infestation	Bb		
		Any other observations	B		
		Preventive Action suggested to customer	Hh		
		Curative action from	Bb		
2		Location	Bb		
		Cleaning / sanitation & Housekeeping Issues	V		
		Structural Issue (Pest harbourages)	Crack was Observed in Floor.		
		Access Issues	V		
		Description of Pest Infestation	It is Serious Threat for Ants.		
		Any other observations	H		
		Preventive Action suggested to customer	Aircurtain Air Will be Checked.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
<p style="text-align: center;">Note: vg</p>					
For Pest Control Experts Authorized Signature. Name: MOHAMMED YOUNUS.A Designation: MANAGER Emp.Code: 001 Phone Number: 9087200011			For M/s. cv, Authorized Signature. Name: Designation: Emp.Code: Phone Number:		

