




PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022




Facility Name & Address: Bluejay Nuts Pvt Ltd , Chittoor	Audited On: 03-07-2024
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. Byragi	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 6303817139	PC Experts Contact Person No: 8248672110




FACILITY SURROUNDING




Facility Surrounding lot of Thick vegetation.

Internal Premises			REVIEW DATE	COMPLETION DATE	
1		Location	Electrical panel room		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Exhaust fan not available and hole was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, flying insects,lizard, Ants and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Exhaust fan should be placed and out side mesh should be placed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

2		Location	RM material receiving area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gap noticed between the wall to sheet		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, flying insects, lizard and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber beading or silicone sealant or form sealant		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
External Premises				REVIEW DATE	COMPLETION DATE
3		Location	Main gate		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Main gate bottom gap noticed		
		Access Issues	Ni		
		Description of Pest Infestation	It is Serious Threat for snakes, rats, Ants,and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber beading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	Backside compound wall		
		Cleaning / sanitation & Housekeeping Issues	Tree branches fall down on the wall		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, lizard, snake, rodent and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Tree branches should be trim on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

5		Location	Canteen back side		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Lot of unused material dumped		
		Description of Pest Infestation	It is Serious Threat for rodent, snakes, other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't allow the material nearby building		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
6		Location	Unused material dumping yard		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Lot of material dumped improper		
		Description of Pest Infestation	It is Serious Threat for rodent, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Material should be kept proper storage		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
7		Location	Waste material dumping yard		
		Cleaning / sanitation & Housekeeping Issues	Lot of Waste material kept at waste material dumping yard		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for rodent, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Waste material should be removed on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

8		Location	Husk checking area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Mesh was damaged condition and gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizard, rodent, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Mesh should be replaced without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
9		Location	Compound wall		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Compound wall gap noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizard, snakes, rodent and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
10		Location	Electrical panel room		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Electrical panel room opened condition		
		Description of Pest Infestation	It is Serious Threat for Ants, lizard, rodent, snakes and other crawling insects & flying insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Doors should be closed condition		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

11		Location	COMPOUND WALL		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gap noticed between the wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, Ants, snakes, lizard rodent and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
12		Location	Conference Hall outer		
		Cleaning / sanitation & Housekeeping Issues	Thick vegetation observed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, Ants, lizard, rodent, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Vegetation should be trim on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
13		Location	RM back side		
		Cleaning / sanitation & Housekeeping Issues	Thick vegetation observed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, lizard, rodent, snakes, and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Vegetation should be trim on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
Note:					
For Pest Control Experts			For M/s. Bluejay Nuts Pvt Ltd ,		
Authorized Signature.			Authorized Signature.		
Name: SURESH KUMAR.V			Name:		
Designation: MANAGER			Designation:		
Emp.Code: 002			Emp.Code:		
Phone Number: 8248672110			Phone Number:		

