




PEST CONTROL EXPERTS



No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022

Facility Name & Address: industry , garden	Audited On: 13-12-2023
Audited By: MOHAMMED YOUNUS.A	
Client Contact Person Name: priya	PC Experts Contact Person Name: MOHAMMED YOUNUS.A
Client Contact Person No: 9633828282	PC Experts Contact Person No: 9087200011

FACILITY SURROUNDING

surrounding

Internal Premises			REVIEW DATE	COMPLETION DATE	
1		Location	Rm emergency		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
External Premises			REVIEW DATE	COMPLETION DATE	
1	Location	Rm emergency			
	Cleaning / sanitation & Housekeeping Issues	Nil			
	Structural Issue (Pest harbourages)	Gaps Observed between Door Frame and Wall			
	Access Issues	Rm emergency dovvbbjghrtgghhjijjhhhhhhhhhhgggggggggghgggg gghhhhhhhh			
	Description of Pest Infestation	It is Serious Threat for Ants.hjjjhghhhhhhhhhhhijnjjjjjnnnnnnnnnnnnnnnnnn nnn			
	Any other observations	Nil			
		Around the Pipeline Gap will be closed with cement			

		<p>Location</p> <p>Cleaning / sanitation & Housekeeping Issues</p> <p>Structural Issues (Best harbourages)</p> <p>Access Issues</p> <p>Description of Pest Infestation</p> <p>Any other observations</p> <p>Preventive Action suggested to customer</p>	<p>mortar or Foam Sealant.</p> <p>We are instructed to Technician for Regular Monitoring.</p> <p>Rm ggjj kg ggggghhj hjkkkkko</p> <p>Nil</p> <p>Gaps Observed Around the Pipe and Wall fghhggggggggg</p> <p>Nil</p> <p>It is Serious Threats for Flies, Lizards, Spiders, & Crawling Insects.</p> <p>Due to rain ddghhhfdjjkj fhkklo fjooo ggjko fgjo dgji dgjo fhj</p> <p>Aircurtain Air Will be Checked. Fgjkkgg fhjkk fghji gghjk ghkk fhkoc nhjk</p> <p>We are instructed to Technician for Regular Monitoring.</p>		
<p>Note: In General your all window mesh will be replaced all windows. Also in Processing area. Fly Killer Machine will be placed to Fly Catcher Machines</p>					
<p>For Pest Control Experts</p> <p>Authorized Signature.</p> <p>Name: MOHAMMED YOUNUS.A</p> <p>Designation: MANAGER</p> <p>Emp.Code: 001</p> <p>Phone Number: 9087200011</p>		<p>Prev  to customer</p> <p>Curative action from</p>	<p>For M/s. industry ,</p> <p>Authorized Signature.</p> <p>Name:</p> <p>Designation:</p> <p>Emp.Code:</p> <p>Phone Number:</p>		
