










Facility Name & Address: M/S. INTERNATIONAL FLAVOURS AND FRAGRANCES INDIA	Audited On: 12-06-2023
Audited By: MOHAMMED YOUNUS.A	
Client Contact Person Name: MR. JINSON JOSEPH	PC Experts Contact Person Name: MOHAMMED YOUNUS.A
Client Contact Person No: 9840987098	PC Experts Contact Person No: 9087200011

FACILITY SURROUNDING

In Our Audit your facility surrounded Thick Vegetation. Major thread for the surrounding is Flying insects, Rodents, Spiders, Snakes & Other Crawling insects.

External Premises			REVIEW DATE	COMPLETION DATE	
1		Location	Waste Material Movement Area	14-07-2023	31-07-2023
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps Observed between the Wall Sheet and Roof Sheet		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Thread for Flies, Lizards, Spiders, & Aphids.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap will be closed with Silicone Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
2		Location	Waste Material Movement Area	14-07-2023	31-07-2023
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps Observed around the Cable.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Thread for Flies, Lizards, Spiders, & Aphids.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Around the Pipeline Gap will be closed with Foam Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

Internal Premises				REVIEW DATE	COMPLETION DATE
1		Location	PANEL ROOM AREA	14-07-2023	31-07-2023
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps Observed Around the Pipe and Wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Thread for Flies, Lizards, Spiders, & Aphids.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Around the Pipeline Gap will be closed with Foam Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
2		Location	PANEL ROOM TO MANMOVEMENT AREA	14-07-2023	31-07-2023
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps Observed Around the Pipe and Wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Thread for Flies, Lizards & Rodents.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Around the Pipeline Gap will be closed with cement mortar or Foam Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	PANEL ROOM TO MANMOVEMENT AREA	14-07-2023	31-07-2023
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Cable tray was Opened Condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Thread for Flies, Lizards, Spiders, & Crawling Insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Cable Trenches will be Properly Closed.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	PANEL ROOM TO MANMOVEMENT AREA	14-07-2023	31-07-2023
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps Observed Around the Pipe and Wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Thread for Flies, Lizards, Spiders, & Crawling Insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Around the Pipeline Gap will be closed with cement mortar or Foam Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

5		Location	LIQUID AREA BACKSIDE	14-07-2023	31-07-2023
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps Observed between the Wall and Roof Sheet		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Thread for Flies, Lizards, Spiders, & Crawling Insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Sheet to Sheet gap will be closed with Proper Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
6		Location	RM AREA OUTER	14-07-2023	31-07-2023
		Cleaning / sanitation & Housekeeping Issues	Water Stagnation Noticed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Thread for Mosquitoes.		
		Any other observations	Area will be levelled with sand to avoid water Stagnation.		
		Preventive Action suggested to customer	Area will be levelled with sand to avoid water Stagnation.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
7		Location	RM AREA OUTER	14-07-2023	31-07-2023
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps Observed Around the Pipe and Sheet		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Thread for Millepedes & Centipedes.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap will be closed with Silicone Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
8		Location	RM AREA OUTER	14-07-2023	31-07-2023
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps Observed Around the Sheet.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Thread for Flies, Rodents, Snakes, Lizards, Spiders, & Aphids.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap closure will be placed between the sheets..		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

Note: Note: In General your all window mesh will be replaced all windows. Also in Processing area. Fly Killer Machine will be placed to Fly Catcher Machines

For Pest Control Experts

Authorized Signature.

Name: MOHAMMED YOUNUS.A

Designation: MANAGER

Emp.Code: 001

Phone Number: 9087200011

A handwritten signature in blue ink, appearing to read "D. med. Yunus.A", enclosed in a light blue rectangular border.

For M/s. M/S. INTERNATIONAL FLAVOURS AND FRAGRANCES INDIA PVT LTD ,

Authorized Signature.

Name:

Designation:

Emp.Code:

Phone Number: