




PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022

Facility Name & Address: Innovative Foods Ltd , Chittoor	Audited On: 28-10-2024
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. Naresh (QC)	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 7994833665	PC Experts Contact Person No: 8248672110

FACILITY SURROUNDING

lot of thick vegetation observed.

External Premises			REVIEW DATE	COMPLETION DATE
	Location	Back side compound wall near manhole		
	Cleaning / sanitation & Housekeeping Issues	Not cleaned properly		
	Structural Issue (Pest harbourages)	Lid not closed properly		
	Access Issues	Vegetation observed		
	Description of Pest Infestation	It is Serious Threat for Cockroaches, rodent, fly, snake, ants and other crawling insects		
	Any other observations	Nil		
	Preventive Action suggested to customer	Vegetation should be removed on regular basis. Lid should be closed, and don't kept waste near by building area.		
	Curative action from	We are instructed to Technician for Regular Monitoring.		

1		Location	Back side of the building area		
		Cleaning / sanitation & Housekeeping Issues	Fire wood dumped on inside road area un even condition		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	We can't able to go and do the service		
		Description of Pest Infestation	It is Serious Threat for Cockroaches, termites, rodent, snake, frog,ants and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Area should be clean always, fire wood dumped to fire wood yard		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
2		Location	Back side of the building		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Waste water out let pipe and manhole lid gap between noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Cockroaches, rodent, mosquito, lizard, snake		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Back side compound wall		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Manhole lid not their		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Cockroaches, mosquito, rodent, snake, lizard, ants and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Manhole lid will be placed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
Note: Nil					

For Pest Control Experts


Authorized Signature.

Name: SURESH KUMAR.V

Designation: MANAGER

Emp.Code: 002

Phone Number: 8248672110

A handwritten signature in blue ink, appearing to read 'Suresh Kumar.V', is written over a light gray rectangular background.

For M/s. Innovative Foods Ltd ,

Authorized Signature.

Name:

Designation:

Emp.Code:

Phone Number: