




Facility Name & Address: Saroj Agro industries , Tumkur	Audited On: 25-11-2023
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. Naveen Kumar	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 9164761942	PC Experts Contact Person No: 9087200011

FACILITY SURROUNDING

lot of thick vegetation observed

Internal Premises			REVIEW DATE	COMPLETION DATE	
1		Location	Back side shutter area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Bottom of the shutter gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, snakes, rodent, cockroach, lizard, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Shutter gap should be closed with rubber breading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
2		Location	Waste material dumping area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Fly catcher machine fasia was damaged		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles and flying insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Fasia should be replaced		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

3		Location	Window frame area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gap observed window frame to Wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, Ants, lizard, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement concrete or rubber breading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
External Premises				REVIEW DATE	COMPLETION DATE
1		Location	Main building surrounding		
		Cleaning / sanitation & Housekeeping Issues	Tree branches touch into the Wall		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizard, flying insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Tree branches should be trim on regular basis		
		We are instructed to Technician for Regular Monitoring.			



2



Curative action from


Location	All window frame
Cleaning / sanitation & Housekeeping Issues	Nil
Structural Issue (Pest harbourages)	Gaps Observed between Window Frame and Wall
Access Issues	Nil
Description of Pest Infestation	It is Serious Threat for Ants, lizard, flying insects
Any other observations	Nil
Preventive Action suggested to customer	Gaps should be closed with cement concrete or silicone sealant
	We are instructed to Technician for Regular Monitoring.

Curative action from



Location	Window mesh
Cleaning / sanitation & Housekeeping Issues	Nil
Structural Issue (Pest harbourages)	Window mesh was damaged
Access Issues	Nil
Description of Pest Infestation	It is Serious Threat for Beetles, ants, lizard, flying insects and other crawling insects
Any other observations	Nil
Preventive Action suggested to customer	Mesh should be replaced
	We are instructed to Technician for Regular Monitoring.

Curative action from



Note: In General your all window mesh will be replaced all windows. Also in Processing area. Fly Killer Machine will be placed to Fly Catcher Machines

For Pest Control Experts


Authorized Signature.

Name: SURESH KUMAR.V

Designation: MANAGER

Emp.Code: 002

Phone Number: 9087200011

A handwritten signature in blue ink, appearing to read 'Suresh Kumar.V', is written over a light gray rectangular background.

For M/s. Saroj Agro industries ,

Authorized Signature.

Name:

Designation:

Emp.Code:

Phone Number: